Star Estimating 118-20 229th St, Cambria Heights, NY 11411,USA

Email: info@starestimating.com

Website: www.starestimating.com

	PAINTING						¢ .
	FAILTING						
1	PT-3: Latex Acrylic Paint, Finish: Flat, Mfg: SHERWIN WILLIAMS, Location: Ceiling	60,183	10%	66,201	sf	\$ -	-
2	PT-10: Latex Acrylic Paint, Finish: Eggshell, Mfg: SHERWIN WILLIAMS, Location: Corridor Walls	117,230	10%	128,953	sf	\$ -	
3	PT-4: Latex Acrylic Paint, Finish: Eggshell, Mfg: SHERWIN WILLIAMS, Location: Fitness	1,375	10%	1,513	sf	\$ -	
4	PT-5: Latex Acrylic Paint, Finish: Eggshell, Mfg: SHERWIN WILLIAMS, Location: Coffee Station	1,056	10%	1,162	sf	\$ -	
5	PT-6: Latex Acrylic Paint, Finish: Eggshell, Mfg: SHERWIN WILLIAMS, Location: Kitchen	660	10%	726	sf	\$ -	
6	PT-7: Latex Acrylic Paint, Finish: Eggshell, Mfg: SHERWIN WILLIAMS, Location: Meeting/Study	671	10%	738	sf	\$ -	
7	PT-9: Latex Acrylic Paint, Finish: Satin, Mfg: SHERWIN WILLIAMS, Location: Bath Units, Restrooms	88,935	10%	97,829	sf	\$ -	
		4:				• •	
UB TOTAL			- 1/			\$	- \$
OVERHEAD & PROFIT (25%)			V			25% \$	- \$
OTAL BID						\$	- \$

Star Estimating